

MAY 29 1991

33

REPLY TO: 6W-SE

Certified Mail #P 341 529 491 - Return Receipt Requested

Bledsoe Partners
Bethany Bank Tower
3908 North Peniel
Bethany, Oklahoma 73008

Re: Requirement to Conduct Mechanical Integrity Test
Inventory No. Well No. Location - Osage County, Oklahoma

OS0803	Boston "A" #3	NE/4, Sec. 01, T 21N, R 07E
OS0804	E-4	NE/4, Sec. 01, T 21N, R 07E

Dear Sir:

Inspection reports dated April 26, 1991, indicate that the referenced well does not have mechanical integrity as required by Osage Underground Injection Control (UIC) regulations [40 CFR §147.2912(a)]. The Environmental Protection Agency (EPA) considers loss of mechanical integrity to be a serious violation of the Osage UIC program regulations. Therefore, you must test mechanical integrity of the well according to 40 CFR §147.2912(a)(1)(i) within 30 days after receipt of this letter. Contact the Osage UIC Office (918-287-4041) at least five days before you test the well so an EPA representative can witness the test [40 CFR §147.2912(a)].

If you do not comply with this letter by the time specified, you will be required to obtain a UIC permit for future well operation. Violation of any Osage UIC program regulation is also a violation of the Safe Drinking Water Act, as amended (42 U.S.C. §300f et seq.) and subject to penalties of up to \$25,000 per day of violation.

Please contact Mr. David Jones [214-655-7165] if you have any questions concerning this letter.

Sincerely yours,

Gus Chavarria
Chief
UIC Permits and Enforcement Section (6W-SE)

cc: BIA, Minerals Branch
Osage UIC Office

6W-SE: JONES:sm:May 15, 1991:DISK:DJ:BLEDSE.58:ENF CODE:G5:

6W-SE
VAN WYK

5-28-91

dmc
5-31-91